

ARROW®

REF PL-00760

Arrow® GlideThru® Peel-Away
Sheath over Dilator

6^{Fr.} 7^{cm}

Dilator accepts .018" dia. or smaller Spring-Wire
Guide. Sheath accepts 6 Fr. or smaller catheter.

Contents:

- 1: GlideThru™ Peel-Away Sheath: 6 Fr. x 2-3/4" (7 cm)
Radiopaque over 6 Fr. Dilator

Rx only Warning: Read all package insert warnings,
precautions, and instructions prior to use. Failure to do so may
result in severe patient injury or death. www.teleflex.com/IFU
Not made with natural rubber latex.
Fluid path components are non-pyrogenic.

ARROW®

REF PL-00760

Arrow® GlideThru® Peel-Away
Sheath over Dilator

6^{Fr.} 7^{cm}

Dilator accepts .018" dia. or smaller Spring-Wire
Guide. Sheath accepts 6 Fr. or smaller catheter.

Contents:

- 1: GlideThru™ Peel-Away Sheath: 6 Fr. x 2-3/4" (7 cm)
Radiopaque over 6 Fr. Dilator

Rx only Warning: Read all package insert warnings,
precautions, and instructions prior to use. Failure to do so may
result in severe patient injury or death. www.teleflex.com/IFU
Not made with natural rubber latex.
Fluid path components are non-pyrogenic.

ARROW®

REF PL-00760

Arrow® GlideThru® Peel-Away
Sheath over Dilator

6^{Fr.} 7^{cm}

Dilator accepts .018" dia. or smaller Spring-Wire
Guide. Sheath accepts 6 Fr. or smaller catheter.

Contents:

- 1: GlideThru™ Peel-Away Sheath: 6 Fr. x 2-3/4" (7 cm)
Radiopaque over 6 Fr. Dilator

Rx only Warning: Read all package insert warnings,
precautions, and instructions prior to use. Failure to do so may
result in severe patient injury or death. www.teleflex.com/IFU
Not made with natural rubber latex.
Fluid path components are non-pyrogenic.



Arrow International LLC
Subsidiary of Teleflex Incorporated
3015 Carrington Mill Blvd.
Morrisville, NC 27560 USA

Teleflex®
www.teleflex.com

LBL068159 R00 (2022-08)

Arrow International LLC
Subsidiary of Teleflex Incorporated
3015 Carrington Mill Blvd.
Morrisville, NC 27560 USA

Teleflex®
www.teleflex.com

LBL068159 R00 (2022-08)

Arrow International LLC
Subsidiary of Teleflex Incorporated
3015 Carrington Mill Blvd.
Morrisville, NC 27560 USA

Teleflex®
www.teleflex.com

LBL068159 R00 (2022-08)